


NOTE: FIXINGS SUPPLIED SEPARATELY UNLESS SPECIFIED






| SAS740 Lights | | | |
|---------------|----------------|---|--------------|
| REF | ITEM No. | Description | Colour |
| 1 | 10188 to 10192 | Emac Hanger | Mill |
| 2 | Various | Support Channel With Location Shoulders (See Worknorm 0739 for Types) | Ral 9005 30% |
| 3 | 364251 | Support Channel Splice | Ral 9005 30% |
| 4 | Various | System 740 Hook Over Bracket (See Worknorm 0783 for Bracket Configurations) | Ral 9005 30% |
| 5 | 401148 | M6 Clamping Bolt | - |
| 6 | Various | System 740 Aluminum Profiles (See Worknorm 0754 for Available Profiles) | Various |
| 7 | Various | System 740 Light Unit (See Worknorms 0454 & 0577 for Types) | Various |
| 8 | Various | System 740 Light Push Fit End Caps (See Worknorm 0754 for Types) | As Profile |
| 9 | 14042 | TCP 180s Splice | Mill |
| 10 | Various | System 740 Lay-in Tile (Optional) | As Profile |
| 11 | 463600 | Light Spill End Cap | Black |
| 12 | 472890 | Joint Light Spill Cap | White |






ISO VIEW (1:15)

ISO DETAILS (1:4)

| REV | DATE | DESCRIPTION | INITIAL |
|-----|------------|-------------|---------|
| A | 09/08/2019 | FIRST ISSUE | --- |
| | | | |
| | | | |
| | | | |



| REV | DATE | DESCRIPTION | INITIAL |
|-----|------------|-------------|---------|
| A | 13/05/2021 | FIRST ISSUE | |
| | | | |
| | | | |
| | | | |
| | | | |



FOR ALL LIGHT ITEM NUMBERS SEE DRG 0771. FOR PROFILE OPTIONS AND ACCESSORIES, SEE DRG 0783.

| REV | DATE | DESCRIPTION | INITIAL |
|-----|------------|-------------|---------|
| A | 13/05/2021 | FIRST ISSUE | --- |
| | | | |
| | | | |
| | | | |